

Vinyl Graphic Application

Clean surface with 70% isopropyl alcohol 2 times using a clean cloth or towel. Wait a minimum of 15 minutes for the surface to dry. Test the surface with 2" quality masking tape. If it has trouble adhering, wait 15 minutes longer for the surface to dry. If it still does not adhere well, rewash the surface with alcohol and allow to dry.

1. Clean Surface

Use a dry cloth to clean the surface.

2. Secure with Tape

Tape graphic in place using masking tape, with the backing paper touching the surface where the graphic will be installed and transfer tape on top surface.

3. Tape in Place

Apply another piece of masking tape (2" wide) across the top of the graphic to make an install hinge

4. Remove Backing Paper

Flip the graphic around and carefully remove the backing paper from the transfer tape. Lift one side of the release liner from the vinyl away and mask.

5. Apply the Graphic

Apply pressure with a squeegee. Work from the top to the bottom, using long stroke parallel to the hinge to avoid trapping air bubbles and to adhere the graphics to the surface.

6. Remove Transfer Tape

Peel the transfer tape away to reveal your Graphics!

